Name	T SCH	ISLER	,		Date	2/23/16		Page	l of /	
Wate	(Please chman M P	Print)						2203		
	cted From			To C	ous Sp	DIALC.	w.o numb	or 2293	877	
)	TOTAL COLL	MERVICE	•	10 0	OUS OP	KING	443			
	Exception Chair	n Marker No.	WW. Bru	Track	Rall	Switch	Con	des	Status	Repair
Item	From	To		No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.			<b>对特别的</b>	'						
2.										
3.										
4.										
-										
5.			fill the British of the State							
<u>6.</u> 7.										
				-						
8, 9,										
Item	COMMENTS		HARLAND REPORT AND AND ADDRESS.				<u> </u>			
Item		6 1.10.00	D.		Daii	,				
			S OBSERV		KITIN					
	NO NEW	DEFEC	5 OBSERV	ED						
					,					
	•								,	
			·							-
	.•									
	Were Switch	in the area	of Inspecte	d Ve	SAME	XONLY N	0			
We	ere all single op							referred to a		O:
Yes	NO_X	oraling moo	namen a co	iootii ig re	od type or	MICHOS HISIGS	area and ope	ratated in e	acn positio	Π Y .
	SPECIAL IN	SPECTIO	N Yes_	N	10 x				¥	
_										
Rea	ison for speci	al Inspect	ion ?							
									4	1
Trac	k Inspector Sig	inature					Supervisory	Crotificati		Mana
	T Ichin						Cuper visory	Oleming()	JII YUMM	11000
	1 this								0	ι



Watci Inspec	( Please thman ted From Hun		G.C4			2-22- her Ville		Page Z Z		79
	Exception Chain	Marker No		Track	Rall	Switch	Cod	lon	C4=4	T
Item	From	To	i allumbar	No.	E/W	No.	Comp.	Defect	Status S/Y/R	Repali Y/N
1.								20,000	OFTIN	1//4
2.			<b>图 10 10 10 10 10 10 10 10 10 10 10 10 10 </b>							
3.										
4.							•			
_	·									
5.				A CONTRACTOR OF THE CONTRACTOR						
6.										
7.				1 ·						•
8. 9.				M						
em	COMMENTS	•								
We	Were Switch	in the are	a of Inspect	ed Ye	es od type sv	No vitches inside	oarea and ope	ratated in e	ach positio	n?
98	Were Switch	rating med	a of Inspect chanism & co	necting ro		Novitches inside	o_ area and ope	ratated in e	ach positio	n?
95	Were Switch ore all single ope	orating med	a of Inspect chanism & co	necting ro	od type sv	vitches inside	o area and ope	ratated in e	ach positio	n?



		nthicu	_		romin					
14	Exception Chair		iiiw.6		Rall	Switch	Cod	-	Status	Repair
Item	From	То	Number		E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.				a	W	484. I-B	5.304	301	У.	N
2. 3.										
4.		·					•			-
7			6051 JULE U ATRICA							
5.				'.	•					
6,										
7.										<del></del>
8.								-		
9.										
<u> </u>			1211年12月1日 第二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十							
em /	COMMENTS Right //	nand of the	straig.	hts.		h fóin Is grin	tica ding	hatter	ed a i	T Fr.
em	Right	nand of	Traig prin	hts.			tic p	hatter	ed or	771
em	Right 1	ofthe	poin	<i>f.</i> /	Vec	ds grin	ding	hatter	edai	T 711
We	Right 1	In the area	of Inspecte	od Ye	Vec	V NO	ding			
We	Were Switch	In the area	of Inspecte	ed Yenecting ro	Vec	No grin	ding			
We	Were Switch ore all single ope	In the area	of Inspecte hanism & co	nd Yenecting ro	es	No grin	ding			



1. 2. 3. 4. 5. 6. 6.	Status efect S/Y/R	Repali Y/N
1. 2. 3. 4. 5. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6.	efect S/Y/R	Y/N
2.		
3.       (1)       (2)       (3)       (4		
4.       5.       6.		
5.        6.		1
6.		
6.		
BOSHEY TO THE TOTAL OF THE TOTA		
7.		
9.		
em COMMENTS		
No ver Defects Noted in Agen	. •	
		-
More Civiled to the area of the season of th		
Were Switch in the area of Inspected Yes NO		
VV OF BILL SINGLE ODERATING MECHANISM & CONECTING FOR TVDA SWITCHES Inside area and operated	ed in each position	יף חנ
Were all single operating mechanism & conecting rod type switches inside area and operatat		•
NO		
SNO		
SPECIAL INSPECTION YesNO		
SPECIAL INSPECTION YesNO	* .	
SPECIAL INSPECTION YesNO	-	
sNO		
SPECIAL INSPECTION Yes NO  Reason for special inspection ?	<u> </u>	
SPECIAL INSPECTION YesNO	tification <u>√am</u>	



	<b>Exception Chair</b>		WWW.E.F.F	Track	Rall	Switch	Co	des	Status	Repair
em	From	To		No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
<u>.  </u>			<b>网络海绵网络</b>							1
2.										
								4	·	
-										
-										
-										
-										
-										
1	COMMENTS						4			
	Were Switch	erating mech	nanism & con	ecting ro	od type sv			eratated in e	each positlo	n?
	Were Switch re all single ope	erating mech	N Yes	ecting ro	od type sv	vitches inside		eratated in e	each positlo	n?



Name	7.50	hister	R. Nei	son	Date	2/17/	110	Page	100 /	
	( Please chman	Print) Inthic	/	То	Can	rden	W.O Numb	er 2210		
	/	· ·				74 ( )				
Item	Exception Chai				Rall	Switch	Coc		Status	Repair
1.	199+20	То		No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
2,	094+00	109420		/			F.305	303	<u> </u>	N
3,	085700	175+00		2	2-		R301	344	<u> </u>	N
4.	070+00	065400		2	E		P301	344	<del>-</del>	
							1	77/	<u> </u>	70
5.	0301020			/	111		J30/	301	V	1.
6.			PERCEPT							
7.		,	<b>FERENCIAL</b>							•
8.			排列的通用值					,		
9.										
Item	COMMENTS									
1	One pr	oken c	oncre	Tel	linti	under	15100	don	AEri	2/
8						108	30/11/19	18.		
3.	SideWo	rarai				C 85	-OMAX	· ,		
1	Sidening	the state of the s	Wear			8/00	max-			
121	Loculate	d 7011	nt briti	ered	4/12	Smeta	1/101	1 over	endk	25%
$\vdash$										-
										-
-			•							
									,	
	Were Switch						0			
We	ere all single op	erating mech	nanism & cor	ecting ro	od type sv	vitches inside	area and ope	ratated in e	ach positio	n ?
Yes	NO/									•
	SPECIAL IN	SPECTIO	N Yes	\	10 2					
Rea	ison for speci	lal inspecti	on ?							
				-	,		•			1
									1	
Trac	k inspector Sig	națure ,	2				Supervisory	Cretificati	on France	Mu
-	100	////	(na. )					~ . ~	11	-
9	whale	_/Vel	you						V	
/										



Inspec	ted From	Idsprin	2	То	Came	den-	Penn			
	Exception Chal	n Marker No.	. WW.EH	Track	Rall	Switch	Coc	les	Status	Repai
Item	From	To	A Combient	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.				54						
4.										
5,				Old Control of the Co						
6.										
7.										
8.										
9.										
	COMMENTS	Ridin	g In	-5/De <	24,02		— Sno	new te		
	COMMENTS	Ridin	g En	-5/De-	=1.0.2		— Sno	rw te	2	
iem	COMMENTS	Ridin	g En	spe	21,02		— Sno	nw te	2	
		Ridin	g En	spe-	=1.02		— Sno	nu te		
								rw te		
	Were Switch	n in the are	a of Inspect	ted Ye	08	NO				in 2
We	<i>Were Switch</i> ore all single op	n in the are	a of Inspect	ted Ye	08	NO				n ?
	<i>Were Switch</i> ore all single op	n in the are	a of Inspect	ted Ye	08	NO				n?
We	Were Switch	n in the are	a of Inspect	fed Ye	es_ od type swi	NO				n?
We	<i>Were Switch</i> ore all single op	n in the are	a of Inspect	fed Ye	08	NO				n?
We	Were Switch pre all single opNO	in the area	a of Inspect chanism & co	fed Ye	es_ od type swi	NO				n ?
We	Were Switch	in the area	a of Inspect chanism & co	fed Ye	es_ od type swi	NO				n?
We	Were Switch pre all single opNO	in the area	a of Inspect chanism & co	fed Ye	es_ od type swi	NO				nn?



mabéc	cted From LUTH				DLD SE	RING	-			
	Exception Chain				Rail	Switch	Cod	les	Status	Repai
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.					-		,			
4.										
- 12	· · · · · · · · · · · · · · · · · · ·									
5.										
6.										
7. 8.	· ·									
9.   em	COMMENTS				L					
				· · ·						
Wees	Were Switch i ere all single ope NO_ <u>ホ</u>	rating med	chanism & cor	ecting ro				ratated in e	each positio	on ?
98	Were Switch	rating med	chanism & cor	ecting ro	id type sw	ritches inside		pratated in e	each positio	on ?



18080	( Please hman ted From Ca	mde		To	Lin	thice	W.O Numb	er ZZ8	532	P
	Every Obel	- Madian No		Tanala	D-11	S. 11. b.				
item	Exception Chai	To								
1.	From	10	AND THE PARTY OF T	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
2.										<del>                                     </del>
3.								-		
4.										
	,									
5.							-			
6.										
7.										,
9.										
9.   m	001111111111									
m T	COMMENTS	11:	New 1	0						
			of Inspected							
We	ore all single op NO SPECIAL IN	erating mec	hanism & con	ecting ro	ed type sv		oarea and ope	ratated in e	each positio	on ?'
Rea	son for spec	ial inspect	ion ?		,					
1 (00										





То	HANUMBERTS STATE OF THE STATE O	No.				ies	Status	Repair
			E/W	No.	Comp.	Defect	S/Y/R	Y/N
	TABLEMENT SECRETATION STATEMENT AND INCIDENT	•						
					·			
	(0.24/0.14/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/							-
		,						
						**************************************	,	
								•
T <b>3</b>								
NO NEI	) detect	- F-5	2 and					
vitch in the are	na of Inspecte	d Ye	98	Ne	0 8			
vitch in the are	na of Inspecte	d Ye	98	Ne	0 8		each positio	n?
	na of Inspecte	d Ye	98	Ne	0 8		each positio	n?
le operating med	ea of Inspecte	d Ye	esod type sw	Ne	0 8		each positio	n ?
	ea of Inspecte	d Ye	escod type sw	Ne	0 8		each positio	n ?
L INSPECTION	ea of Inspecte chanism & cor	d Ye	esod type sw	Ne	0 8		each positio	n?
le operating med	ea of Inspecte chanism & cor	d Ye	esod type sw	Ne	0 8		each positio	n?
L INSPECTION	ea of Inspecte chanism & cor	d Ye	esod type sw	Ne	0 8		each positio	n?
L INSPECTION  Decial Inspec	ea of Inspecte chanism & cor	d Ye	esod type sw	//itches inside	o	eratated in e	1	 
L INSPECTION	ea of Inspecte chanism & cor ON Yes ction ?	d Ye	esod type sw	//itches inside	0 8	eratated in e	1	 
		No new defeat	No new doferts E	No new defects Found	No new defeats Farming	No new defects Found	No new defeats Found	



Item		In Marker No.		Track	Rall	Switch	Cod	doe	Status	1 2
Iraill	From	To			E/W	No.	Comp.	Defect	S/Y/R	Repai Y/N
1.				•			GGIIIDE	Dalace	GITIN	T/N
2.			Mark Mark	10.00					· · · · · · · · · · · · · · · · · · ·	
3.	·		沙湿 物质量器							
4.										
	,									
5.	'			amin una arigum range .						
8.										
7.										
8.										
9.	COMMENTS									
士										
We	ere all single op		of Inspecte			No ltches inside	Oarea and ope	ratated in e	each positio	n?
We	Were Switch	perating mec	of Inspecte	necting ro		No litches inside	O area and ope	ratated in e	ach positio	n?
8	Were Switch	perating med	of Inspecte hanism & cor	necting ro	d type sw	No itches inside	Oarea and ope	ratated in e	ach positio	n?



apac	cted From	1091 H	Ave yaid				•			
	Exception Chair	n Marker No.	WW.EAR	Track	Rall	Switch	Co	ies	Status	Repair
tem	From	To	Migration of the second	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.						1				
3.										
4.										
-					· ·					
5										
6.					-	3				
7.										
8. 9.										
9. <u> </u> m	COMMENTS		<b>提得到到</b> 2012年							
<b>9</b>	ere all single op	erating med	ON Yes_	necting ro		Witches inside		eratated in e	each position	on ?
Trac	ck inspector Si	gnature		M	1		Supervisor	/ Cretificat	on Jan	rken





ch Codes Status Repaired Repaired Status Repaired Status Repaired Status Repaired Repaired Status Repaired Repai
ndedinarea
NO
nside area and operatated in each position?
· · · · · · · · · · · · · · · · · · ·



Name Watci	( Please hman ted From		voj	To	Date Ca m	2-12-2. den Yak	W.O Numb	Pag <b>e</b> er	63.5	
	Exception Chair	n Marker No.	TEREW ENTER	Track	Rall	Switch	Cod	len	Status	Bonda
Item	From	То	A NUMBER	No.	E/W	No.	Comp.	Defect	S/Y/R	Repair Y/N
1.		11.5	REPRESENTED.		' '.					
2.						1				
3.										
4.			Managara Bi				<u> </u>			
- 5, - 6,		AND ASSESSMENT OF THE PROPERTY								
7.		· · · · · ·								,
8.						· ·				
9,					1 1					
Item	COMMENTS				1				-	·
)———										
	ore all single op		of Inspecte			Notiches inside		eratated in e	each position	on ?
/es	NO									a.
	SPECIAL IN	ISPECTIC	N Yes_		40_C			-		
Rea	son for spec	ial Inspect	lon ?		,				<u> </u>	
Trac	k Inspector Sig	gnature (wel)	Ba	Ü	1		Supervisory	Cretificati	on fam	<u>Me</u> ur



apac	ited From Carf	zer VIII.		ТО	Colas	pring				
	Exception Chair		W. Ditt.		Rall	Switch	Coc	les	Status	Repair
am	From	То	in Lumbert	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.						,				
2.		1.				1		-		
) <u>.                                    </u>					-	.,	-			
					-		,			
: +			li massan oloh politika da bosa Namelika Messah paking Si							
- 1										
-	COMMENTS			Pefe<	c+5 1	noted	in t	frea		
).   n	COMMENTS			Pefec	c+5 /	noted	in t	frea		
-				Pefec	c+5 /	noted	in t	Frea		
	COMMENTS			Pefes	c+5, ,	rotes	in t	frea		
		100 1	vew 1					frea		
	Were Switch	No 1	Vew /	d Ye		No	0			
We	<i>Were Switch</i> ere all single op	No 1	Vew /	d Ye		No	0			on ?
	Were Switch	No 1	Vew /	d Ye		No	0			on ?
We	<i>Were Switch</i> ere all single op	in the area erating mech	of Inspecte	d Ye	esod type sw	No	0			on ?
We	<i>Were Switch</i> ere all single op	in the area erating mech	of Inspecte	d Ye		No	0			on ?
We	<i>Were Switch</i> ere all single op	In the area erating mech	of Inspectenanism & con	d Ye	esod type sw	No	0			on ?





Watchman Nel Collinspected From House Valley  Exception Chain Marker No. W. Track Rall Switch Codes Status Item From To Number No. E/W No. Comp. Defect S/Y/R  1. 2. 3. 4. 5. 6. 7. 8.	7/"
Exception Chain Marker No.   W.C.   Track   Rall   Switch   Codes   Status	
Item         From         To         Number No.         E/W         No.         Comp.         Defect         S/Y/R           1.	Repair
1. 2. 3. 4. 5. 6. 7.	Y/N
3. 4. 5. 6. 7. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	1
4. 5. 6. 7. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	
5	
6.       7.	
6.       7.	
7.	
Company of the Control of the Contro	.,,
A SUPPLIES WAS ARRESTED BY THE PARTY OF THE	-
9.	-
em COMMENTS	L .
No new defects insted in area	
Track inspection Comploto	
THE TRANSPORT OF THE PARTY OF T	
Were Switch in the area of inspected YesNO	
Were all single operating mechanism & conecting rod type switches inside area and operatated in each positi	on ?
sNO	
CDECIAL INCREASION AND	
SPECIAL INSPECTION Yes NO	
Reason for special Inspection ?	
	1
	1//
Track Inspector Signature Supervisory Cretification	un/1/ll
	77
1/1 La La Carlana	
// ( le nous / )	
	MIN F
	J.
	量度。

	Exception Chair	Marker No.		Track	Rall	Switch	Coo	den	Status	Repair
em	From	То	AND ADDRESS.		E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	110111	- 1	2/632/64/03/62			110.	Gompa	Dalace	3/1/14	T/N
2.						,				
3.										
1.										
/										_
,										
1.										
						9-7-3-7-5				
1			Mark State (1984)							
			Manufation 1							
-	COMMENTS		TOTAL STREET, TOTAL STREET, THE			1 11				
		NO	new l	12 fac		votes		Mac		
		N8	New L			voted		Me		
m										
We		ı in the are	a of Inspected	d Ye	08 -		0			on ?
We	Were Switch	In the are	e of Inspecte	d Ye	08 -		0			on ?



	Exception Chain Marker No.	THE WAR THE	Track	Rall	Świtch	Cod	les	Status	Repair
Item	From To	Make Company	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	237405		_/_			K301	332	9	NA
2.					:			· · · · · · · · · · · · · · · · · · ·	
3.				-					
								7	
5,			.'						
6.		4401-00-581							
7.									
8.		Heleng teller							
9.	COMMENTS								
	Six(b) Ties	Pump	Tra	c K iws		conp	olote		
	Six(h) Hes	Pump	.7			(omp	10/2		
We	Were Switch in the areasers all single operating med	a of Inspecte	Trans d Ye	c K iws	pectin	0		each positio	on ?
8	Were Switch in the are pre all single operating med NO SPECIAL INSPECTION	e of Inspecte	Transfer of Year	c K iws	pectin	0		each positio	on ?
8	Were Switch in the are ere all single operating med	e of Inspecte	Transfer of Year	es_	pectin	0		each positio	on ?



	Exception Chain	Marker No.		Track	Rall	Switch	Cod	les	Status	Repai
tem	From	To	Mikumband		E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										1///
2.		•	PART AND L		. 1	1				
3.		•	羽尾 纳英维斯						•	
4.										
5.			<b>一种流激性</b>							
8.			With Author							
7.										
3,			<b>建设建筑等的</b>							
9.			The Library							
	Were Switch		a of Inspecte		98					
We	Were Switch	erating me	<b>a of Inspect</b> e	necting ro		ritches inside		eratated in e	each positio	on ?



	hman	utheru	4/e	То	C. 11	spring	W.O Numb	er_2 <u>27</u>	18143	3/1
	Exception Chair	Marker No.	W. C.	Track	Rall	Switch	Cod	08	Status	Repair
Item	From	To	W. Under		E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.				•					- 1	
2.		•								
3.										
4.										
_	, ,									
5,-										
6.										.9
7.										•
8.										
9.										
m	COMMENTS	iNSIDE	<del></del>		,					
	Trac K area	IN Spec	tio N	Cs mp	lote	No mo			Mared	( Å )
	aieu	iù spec		(smp	Tote				Mared	1 Å)
	A I CA  Were Switch	In the area	Fin N	ed Ye	s	No Ale	u do f	ects		1 1
We	area	In the area	Fin N	ed Ye	s	No Ale	u do f	ects		i i)
We	Were Switch	In the area	of Inspecte	ed Ye	s	No Ale	u do f	ects		ı Al
We	Were Switch	In the area erating meci	of Inspecter	ed Ye	s	No Ale	u do f	ects		n?

